

# MULTIPLICEO

ISTRUZIONI DI MONTAGGIO  
*ASSEMBLY INSTRUCTIONS*

**fantoni**

**Index**

3	90
<b>Avvertenze</b>	<b>Contenitori</b>
<b>Warnings</b>	<b>Storage cabinets</b>
	F65CBN01 - F65CBN02 - F63CBH03
4	98
<b>Scrivanie direzionali - Cuoietto</b>	<b>Pannellature modulari</b>
<b>Executive desks - Split leather</b>	<b>Modular panels</b>
F65DK100 - F65DK102 - F65DPM02	F65PNW17 - F63PNW17 - F65PNK53 - F63PNK53
F65DK101 - F65DK103 - F65DPM25	F65PNK55 - F63PNK55
19	120
<b>Scrivanie direzionali - Impiallacciato</b>	<b>Accessori</b>
<b>Executive desks - Veneer</b>	<b>Accessories</b>
F63DK100 - F63DK101 - F63DPM02	F90CD001 - F65BSF00
F63DK102 - F63DPM25 - F63DPM35	
35	
<b>Tavoli</b>	
<b>Tables</b>	
F65TBM05 - F65TBM00 - F63TBM00 - F65TBM01	
F65TBM02 - F65TBM03 - F65TBM04 - F65CR000	
56	
<b>Elementi per tavoli</b>	
<b>Fittings for tables</b>	
F65TE000 - F65TE001 - F65TE002 - F65TE003	
F65CR000	
66	
<b>Mobili di servizio e cassetriere</b>	
<b>Side cabinets and drawer units</b>	
F65SCN15 - F65SCN21 - F65SCS22 - F63SCS22	
F65PSN51 - F65PSN53 - F65PSS51 - F65PSS53	
F63PSS51 - F63PSS53 - F65CBF03 - F65CBF02	
F65TPZ67 + F65SN15	



### AVVERTENZE GENERALI DI SICUREZZA

Nello svolgere le operazioni di montaggio possono presentarsi diversi rischi connessi alle specifiche attività quali ad esempio l'utilizzo di attrezzi manuali, meccanici ed elettrici; al fine di consentire lo svolgimento delle operazioni in condizioni di sicurezza vi chiediamo di seguire le indicazioni sotto riportate:

1. UTILIZZARE ATTREZZATURE IDONEE E CONFORMI ALLE NORMATIVE VIGENTI DOPO AVERNE VERIFICATO IL BUONO STATO DI MANUTENZIONE.
2. UTILIZZARE LE ATTREZZATURE SECONDO LE ISTRUZIONI D'USO ED EVITARE COMPORTAMENTI CHE POSSANO ARRECARE DANNO AD ALTRE PERSONE.
3. DURANTE LE OPERAZIONI DEPOSITARE LE ATTREZZATURE E GLI ARREDI IN POSIZIONI SICURE E STABILI.
4. NELLO SVOLGERE LAVORAZIONI CHE COMPORTANO RISCHI PER LA SALUTE, UTILIZZARE ADEGUATI DISPOSITIVI DI PROTEZIONE INDIVIDUALI QUALI GUANTI, OCCHIALI PROTETTIVI, MASCHERINE ANTIPOVERE.

La Fantoni S.p.A. declina ogni responsabilità nel caso si verificassero danni a cose e/o persone causati da errori nel montaggio, da manomissioni degli elementi e dalla mancata osservazione delle presenti istruzioni.

Si riserva inoltre, il diritto di apportare ai suoi prodotti in qualsiasi momento e senza preavviso, modifiche ritenute opportune per esigenze tecnico-commerciali.

### SAFETY GENERAL WARNINGS

By making the built-up operation, there hight be several risks directy connected to that specific activity,as for example, the use of electrical, mechanical and manual items.The purpose of these warnings is to prevent injuries and damages, that came from an unsafety behavior, so we ask you to follow these instruction below:

1. ALWAYS USE SUITABLE AND PERSUANT TO THE ACTUAL LAW ITEMS, AFTER YOU'VE MAKE SHURE THAT THE INSTRUMENTS ARE GOOD TO WORK.
2. ALWAYS REMIND THE INSTRUCTION OF USE OF THE ITEMS AND MIND NOT TO KEEP A BEHAVE THAT COULD BE DANGEROUS OR HARMFUL FOR OTHER PEOPLE.
3. WHILE THE OPERATIONS ARE IN PROGRESS, ALWAYS STOCK THE ITEMS OR EQUIPMENT IN SAFE PLACE.
4. WHILE DOING SOME WORKS THAT MAY BE DANGEROUS FOR YOUR HEALTH, ALWAY USE THE PROPER PROTECTION GAUNTLETS, PROTECTION GLASSES, DUST GRILLE.


Fantoni S.p.A. will not take the responsability in the event of damages or injuries to thing and people caused by tempering, mistakes of assemblage or by no observance of the included instructions.

We also riserve ourselves the right to make any changes at any time to our products for technical-commercial reasons without notice.


Revisione	Data	Descrizione	Redatto da	Approvato da
0	31/07/2015	Prima emissione	Arianna Dorissa	Andrea Bonamigo
1				
2				
3				
4				

# MULTIPLICEO


Scrivanie direzionali - Cuoietto  
*Executive desks - Split leather*




F65DK100




F65DK102




F65DPM02





F65DK101








F65DK103






F65DPM25






























**B**





















# MULTIPLICEO


Scrivanie direzionali - Impiallacciato  
*Executive desks - Veneer*




F63DK100




F63DK101





F63DPM02








F63DK102






F63DPM25  
F63DPM35
















































**E-V2**









# MULTIPLICEO


Tavoli  
*Tables*




F65TBM05




F65TBM00




F63TBM00





F65TBM01  
F65TBM02







F65TBM03  
F65TBM04







F65CR000























**A**



























**A**



**B**



**A**















# MULTIPLICEO


Elementi per tavoli  
*Fitting for tables*




F65TE000




F65TE001





F65TE002







F65TE003







F65CR000



**A**



**B**




















# MULTIPLICEO

Mobili di servizio e cassetriere


*Side cabinets and drawer units*




F65SCN15




F65SCN21




F65SCS22  
F63SCS22





F65PSN51 - F65PSN53  
F65PSS51 - F65PSS53  
F63PSS51 - F63PSS53







F65CBF03  
F65CBF02







F65TPZ67 + F65SCN15






































































**A**













# MULTIPLICEO


Contenitori  
*Storage cabinets*





F65CBN01








F65CBN02











F63CBH03



**A**
















C




D


# MULTIPLICEO

Pannellature modulari


*Modular panels*





F65PNW17  
F63PNW17







F65PNK53  
F63PNK53








F65PNK55  
F63PNK55



**A**




















**A**



**B**



















G








**A**











C














# MULTIPLICEO



Accessori  
Accessories



F90CD001

F65BSF00



**A**



**Fantoni SpA**

I-33010 Osoppo/Udine  
Telefono +39 0432 9761  
Telefax +39 0432 986266  
[info@fantoni.it](mailto:info@fantoni.it)  
[www.fantoni.it](http://www.fantoni.it)